



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Internal 2009
m1047/0022
0001

Inspection Report Minerals Regulatory Program January 21, 2010

Reviewed:

Mine Name: Uintah County Asphalt Mine	Permit Number: M/047/0022
Operator Name: Uintah County Road Department	Inspection Date: November 18, 2009
Inspector(s): L Heppler	Time: 4:00 pm
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 11-13-2009 **Bond Amount:** \$115,900 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site was last inspected as a Large mine site on 11/26/2007

Inspection Summary: Large stockpiles of asphalt are stored on site. Every effort should be made to salvage top soil and stockpile enough topsoil on site for future reclamation.

Photos were taken to document site conditions and are attached.

Conclusions and Recommendations: Permit NOI indicates 44 acres of disturbance. Operator should update permit and reclaim area no longer used by Uintah County and reduce the disturbed acres in the permit. The acres disturbed by mining should be included in the permit by the operator who has fiduciary liability for the current operation. OGM to continue annual inspections and monitor the site when in the area.


Inspector's Signature

LAH:vs

cc: Quentin Johnson, Uintah County Road Department

O:\M047-Uintah\M0470022-UintahAsphaltRidge\inspections\Insp-11182009.doc





Asphalt stockpiles stored on site